




1. TAB OF COVER TIE IS INSERTED INTO HOLE IN BASE.
2. WASHERS AND NUTS ARE MANUALLY ASSEMBLED ONTO STUD AND NUTS ARE FINGER TIGHTENED ANYWHERE BELOW TOP OF STUD.
3. TORQUE REQUIRED FOR HEX NUT IN USER APPLICATION TO BE 4.0 - 5.0 NEWTON METERS (35-44 IN-LBS).

- # METRIC

	UNLESS OTHERWISE SPECIFIED, DIMENSIONS ARE IN MILLIMETERS. DIMENSIONS IN BRACKETS () ARE INCHES
	UNLESS OTHERWISE SPECIFIED, DIMENSIONS DO NOT INCLUDE PLATING.
◎	DENOTES CRITICAL CHARACTERISTICS.
CPK	DENOTES CPK DIMENSIONS, -MINIMUM CPK VALUE
ST	DENOTES A CHARACTERISTIC THAT PROVIDES AN INDICATION OF PROCESS PERFORMANCE. PROCEDURE FOR MEASUREMENT AND TRACKING TO BE DEFINED IN LITTELFUSE INSPECTION INSTRUCTIONS
CP	DENOTES CP DIMENSIONS, -MINIMUM CP VALUE MUST BE WITHIN THE DIMENSIONAL LIMITATIONS SHOWN ON DRAWING AND INITIALLY LOCATED TO ALLOW FOR MAXIMUM TOOL LIFE

[illegible]